



1 Step 1: Clean

To start - the surface must be clean, whether using it on an auto windshield or a glass shower door. On the car windshield we recommend a high quality glass cleaner preferably without ammonia or high alcohol content. Clean it well, that often means a few times, making sure you remove all the grease and bugs to allow μ BRITANIUM to bond to the glass.

2 Step 2: Apply

Hold the applicator between the thumb and fingers with the pad down and level over the windshield. Squeeze the wings together until a popping sound is heard and liquid is released onto the pad. Use immediately.

Wipe the soft pad of the applicator over the glass up and down then side to side to ensure the glass is well covered. Avoid painted surfaces. Remove liquid from non-glass surfaces with dry paper towel.

3 Step 3: Dry

Wipe the glass with a clean dry paper towel immediately after μ BRITANIUM has been applied to the entire windshield. Failure to wipe immediately may cause hazing that requires additional buffing with a clean dry paper towel.

Note: One single-use applicator will treat one windshield plus two side windows.

- * Do not let μ BRITANIUM air dry onto windshield.
- * When applying to large surface areas treat and dry one half at a time.
- * Application conditions: Do not use in temperatures colder than 50° F or hotter than 90° F or in excessively humid conditions.
- * Once applied, μ BRITANIUM Glass Treatment can be reapplied as needed.
- * Cleaning glass with ordinary glass cleaners will not affect product durability.